Inspection Report-2010 Maruti Celerio ZXI AMT(O)

| Exterior | | | | | |
|---|-------------------|------------------------|-----|--|--|
| Body | _ | | _ | | |
| No Rusting on outer | Yes | Left Rear Door is | Yes | | |
| body panels. | | repainted. | | | |
| Right side pillar A, B & | Yes | Left Rear Door is | Yes | | |
| C has no damage and | | Repaired. | | | |
| factory seal intact. | | | | | |
| Left side pillar A, B & C | Yes | Dickie is Repainted. | Yes | | |
| has no damage and | | | | | |
| factory seal intact. | | | | | |
| Front bumper is | Yes | Hood is Repainted. | Yes | | |
| repainted. | | | | | |
| Back bumper is | Yes | Right Fender is | Yes | | |
| repainted. | | Repainted. | | | |
| Right Front Door is | Yes | Right quarter Panel is | Yes | | |
| repainted. | | Repainted. | | | |
| Left Front Door is | Yes | Left quarter panel is | Yes | | |
| repainted. | | repainted. | | | |
| Right Rear Door is | No | Left Rocker is | Yes | | |
| Repainted. | | repainted. | | | |
| Right Rocker is | No | | | | |
| repainted. | | | | | |
| EXTERIOR COMPONE | NTS | • | • | | |
| All door handles are | Yes | Wipers are working | Yes | | |
| operating properly. | | properly. | | | |
| GLASSES | | 1, , | • | | |
| No scratch & cracks on | Yes | | | | |
| LIGHTS | | | • | | |
| Head lights, Tail lights a | No | | | | |
| Head lights don't have a | Yes | | | | |
| <u> </u> | | | | | |
| Interior | | | | | |
| AIR CONDITIONER | | | | | |
| Vent air flow operate as | | No | | | |
| | | | | | |
| Heating & Air Cooling condition operating as designed. BODY PANEL Yes | | | | | |
| No scratch, dent or disc | oloration in inta | rior hady panala | Yes | | |
| , | | | | | |
| No Rusting in trunk floor | No | | | | |
| INTERIOR COMPONEN | Mo | | | | |
| Interior door handles are | No | | | | |
| Horn is functioning prop | Yes | | | | |
| All knobs and switches a | Yes | | | | |
| SEATS No stain waar 8 taar in aasta | | | | | |
| No stain, wear & tear in | | No | | | |
| | | | | | |
| Engine | | | | | |

| BATTERY | | | | | | | |
|----------------------------|-----|---------------------|-----|--|--|--|--|
| Battery condition is good | No | | | | | | |
| FIXTURES | | | | | | | |
| No bodywork or rusting i | Yes | | | | | | |
| No rusting or bodywork | Yes | | | | | | |
| Factory bolts and seals | No | | | | | | |
| HEALTH | | | • | | | | |
| Engine is intact and no o | No | | | | | | |
| No blowback observed in | No | | | | | | |
| Engine is free of oil leak | Yes | | | | | | |
| | | | | | | | |
| Road Test | | | | | | | |
| MALFUNCTION | | | _ | | | | |
| No abnormal noise | Yes | No abnormal noise | Yes | | | | |
| from engine. | | from gear box. | | | | | |
| No abnormal noise | Yes | No noise or leakage | Yes | | | | |
| from tyre. | | from axle. | | | | | |
| PEDAL | | | | | | | |
| Transmission/ clutch ope | No | | | | | | |
| Brake is functioning prop | No | | | | | | |
| STABILITY | | | | | | | |
| Vehicle doesn't pull to th | Yes | | | | | | |
| Vehicle drives straight of | No | | | | | | |
| SUSPENSION | | | | | | | |
| No abnormal noise or vii | Yes | | | | | | |
| | | | | | | | |
| Tyres | | | | | | | |
| FRONT LEFT TYRE | | | | | | | |
| No cut marks or hardeni | Yes | | | | | | |
| No scratch, rusting and | Yes | | | | | | |
| FRONT RIGHT TYRE | | | | | | | |
| No cut marks or hardeni | No | | | | | | |
| No scratch, rusting and | Yes | | | | | | |
| REAR LEFT TYRE | | | | | | | |
| No cut marks or hardeni | Yes | | | | | | |
| No scratch, rusting and | No | | | | | | |
| REAR RIGHT TYRE | | | | | | | |
| No cut marks or hardeni | No | | | | | | |
| No scratch, rusting and | No | | | | | | |
| SPARE TYRE | | | | | | | |
| Spare tyre is present. | Yes | | | | | | |