## Inspection Report-2010 Hyundai i10 Magna 1.1 iRDE2

Exterior			
Body			
No Rusting on outer	No	Left Rear Door is	No
body panels.		repainted.	
Right side pillar A, B &	No	Left Rear Door is	No
C has no damage and		Repaired.	
factory seal intact.			
Left side pillar A, B & C	No	Dickie is Repainted.	No
has no damage and			
factory seal intact.			
Front bumper is	No	Hood is Repainted.	Yes
repainted.			
Back bumper is	No	Right Fender is	No
repainted.		Repainted.	
Right Front Door is	No	Right quarter Panel is	No
repainted.		Repainted.	
Left Front Door is	No	Left quarter panel is	No
repainted.		repainted.	
Right Rear Door is	No	Left Rocker is	No
Repainted.		repainted.	
Right Rocker is	No	ropamiear	
repainted.	7.00		
EXTERIOR COMPONE	NTS		
All door handles are	Yes	Wipers are working	Yes
operating properly.	700	properly.	100
GLASSES		ргорену.	
No scratch & cracks on	windshields and ı	windows	No
LIGHTS	wiriusriieius ariu v	williaows.	1100
	nd other lights fu	nctioning normally	Yes
Head lights, Tail lights and other lights functioning normally.  Head lights don't have any moisture formation.			Yes
rieau lights don't have a	163		
Interior			
AIR CONDITIONER	ala a i aura a al		144
Vent air flow operate as	No		
Heating & Air Cooling co	No		
BODY PANEL	.1 (		N.C.
No scratch, dent or disc	No		
No Rusting in trunk floor	No		
INTERIOR COMPONE			Tv
Interior door handles are	Yes		
Horn is functioning prop	Yes		
0111	Yes		
All knobs and switches a			
All knobs and switches a <b>SEATS</b> No stain, wear & tear in			No

BATTERY					
Battery condition is good	Yes				
FIXTURES					
No bodywork or rusting	No				
No rusting or bodywork	No				
Factory bolts and seals	Yes				
HEALTH			•		
Engine is intact and no	Yes				
No blowback observed i	No				
Engine is free of oil leak	Yes				
Road Test					
MALFUNCTION					
No abnormal noise	No	No abnormal noise	No		
from engine.		from gear box.			
No abnormal noise	No	No noise or leakage	No		
from tyre.		from axle.			
PEDAL					
Transmission/ clutch op	Yes				
Brake is functioning pro	Yes				
STABILITY					
Vehicle doesn't pull to the side when brake is applied.			Yes		
Vehicle drives straight on level surface.			Yes		
SUSPENSION					
No abnormal noise or vibration from suspension.			No		
Tyres					
FRONT LEFT TYRE					
No cut marks or harden	No				
No scratch, rusting and	No				
FRONT RIGHT TYRE					
No cut marks or harden	No				
No scratch, rusting and	No				
REAR LEFT TYRE					
No cut marks or harden	No				
No scratch, rusting and	No				
REAR RIGHT TYRE					
No cut marks or harden	No				
No scratch, rusting and	No				
SPARE TYRE					
Spare tyre is present.	Yes				