Inspection Report-2014 Maruti Swift VDI

Exterior					
Body					
No Rusting on outer	No	Left Rear Door is	No		
body panels.		repainted.			
Right side pillar A, B &	No	Left Rear Door is	No		
C has no damage and		Repaired.			
factory seal intact.					
Left side pillar A, B & C	No	Dickie is Repainted.	No		
has no damage and					
factory seal intact.					
Front bumper is	No	Hood is Repainted.	No		
repainted.					
Back bumper is	No	Right Fender is	No		
repainted.		Repainted.			
Right Front Door is	No	Right quarter Panel is	No		
repainted.		Repainted.			
Left Front Door is	No	Left quarter panel is	No		
repainted.		repainted.			
, Right Rear Door is	No	Left Rocker is	No		
Repainted.		repainted.			
Right Rocker is	No				
repainted.					
EXTERIOR COMPONE	NTS				
All door handles are	Yes	Wipers are working	Yes		
operating properly.		properly.			
GLASSES					
No scratch & cracks on windshields and windows.					
LIGHTS		•			
Head lights, Tail lights a	Yes				
Head lights don't have any moisture formation.			Yes		
ricaa ngrite derit nave a	1.00				
Interior					
AIR CONDITIONER					
Vent air flow operate as	No				
Heating & Air Cooling co	No				
BODY PANEL	- le ve lie ve in instanten har de				
No scratch, dent or disc	No				
No Rusting in trunk floor	No				
INTERIOR COMPONEN			Mar		
Interior door handles are	Yes				
Horn is functioning prop	Yes				
All knobs and switches a	Yes				
SEATS					
No stain, wear & tear in	No				
Engine					

BATTERY					
Battery condition is go	Yes				
FIXTURES					
No bodywork or rusting	No				
No rusting or bodywork in apron.			No		
Factory bolts and seals of bonnet frame are intact.			No		
HEALTH					
Engine is intact and no overhauling done before.			No		
No blowback observed in the Engine.			No		
Engine is free of oil leakage.			Yes		
	-				
Road Test					
MALFUNCTION					
No abnormal noise	No	No abnormal noise	Yes		
from engine.		from gear box.			
No abnormal noise	No	No noise or leakage	No		
from tyre.		from axle.			
PEDAL					
Transmission/ clutch o	Yes				
Brake is functioning pr	Yes				
STABILITY					
Vehicle doesn't pull to the side when brake is applied.			Yes		
Vehicle drives straight on level surface.			Yes		
SUSPENSION					
No abnormal noise or	No				
Tyres FRONT LEFT TYRE					
No cut marks or hardening is observed in tyre.			No		
	No				
No scratch, rusting and damage observed in rim. No FRONT RIGHT TYRE No					
No cut marks or harde		n turo	No		
No scratch, rusting and	No				
REAR LEFT TYRE	a damaye observe				
	nina is observed ir) tyre	No		
No cut marks or hardening is observed in tyre. No scratch, rusting and damage observed in rim.			No		
REAR RIGHT TYRE	a damayo observe	G 1			
No cut marks or harde	nina is observed in) tyre	No		
No scratch, rusting and	No				
SPARE TYRE	a damayo obsolve		1,40		
Spare tyre is present.	Yes				
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		