

Inspection Report-2015 Maruti Alto K10 LXI

Exterior

Body

No Rusting on outer body panels.	Yes	Left Rear Door is repainted.	Yes
Right side pillar A, B & C has no damage and factory seal intact.	Yes	Left Rear Door is Repaired.	Yes
Left side pillar A, B & C has no damage and factory seal intact.	Yes	Dickie is Repainted.	Yes
Front bumper is repainted.	Yes	Hood is Repainted.	Yes
Back bumper is repainted.	Yes	Right Fender is Repainted.	Yes
Right Front Door is repainted.	Yes	Right quarter Panel is Repainted.	Yes
Left Front Door is repainted.	Yes	Left quarter panel is repainted.	Yes
Right Rear Door is Repainted.	No	Left Rocker is repainted.	Yes
Right Rocker is repainted.	No		

EXTERIOR COMPONENTS

All door handles are operating properly.	Yes	Wipers are working properly.	Yes
--	-----	------------------------------	-----

GLASSES

No scratch & cracks on windshields and windows.	Yes
---	-----

LIGHTS

Head lights, Tail lights and other lights functioning normally.	No
Head lights don't have any moisture formation.	Yes

Interior

AIR CONDITIONER

Vent air flow operate as designed.	No
Heating & Air Cooling condition operating as designed.	Yes

BODY PANEL

No scratch, dent or discoloration in interior body panels.	No
No Rusting in trunk floor.	No

INTERIOR COMPONENTS

Interior door handles are operating properly.	No
Horn is functioning properly.	Yes
All knobs and switches are operating smoothly.	Yes

SEATS

No stain, wear & tear in seats.	No
---------------------------------	----

Engine

BATTERY			
Battery condition is good.			No
FIXTURES			
No bodywork or rusting in the firewall.			Yes
No rusting or bodywork in apron.			Yes
Factory bolts and seals of bonnet frame are intact.			No
HEALTH			
Engine is intact and no overhauling done before.			No
No blowback observed in the Engine.			No
Engine is free of oil leakage.			Yes
Road Test			
MALFUNCTION			
No abnormal noise from engine.	Yes	No abnormal noise from gear box.	Yes
No abnormal noise from tyre.	Yes	No noise or leakage from axle.	Yes
PEDAL			
Transmission/ clutch operates properly with no slipping.			No
Brake is functioning properly with no slipping and free of noise.			No
STABILITY			
Vehicle doesn't pull to the side when brake is applied.			Yes
Vehicle drives straight on level surface.			No
SUSPENSION			
No abnormal noise or vibration from suspension.			Yes
Tyres			
FRONT LEFT TYRE			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			Yes
FRONT RIGHT TYRE			
No cut marks or hardening is observed in tyre.			No
No scratch, rusting and damage observed in rim.			Yes
REAR LEFT TYRE			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			No
REAR RIGHT TYRE			
No cut marks or hardening is observed in tyre.			No
No scratch, rusting and damage observed in rim.			No
SPARE TYRE			
Spare tyre is present.			Yes