

# Inspection Report-2016 Maruti Baleno Delta 1.2

## Exterior

### Body

No Rusting on outer body panels.	No	Left Rear Door is repainted.	No
Right side pillar A, B & C has no damage and factory seal intact.	No	Left Rear Door is Repaired.	No
Left side pillar A, B & C has no damage and factory seal intact.	No	Dickie is Repainted.	No
Front bumper is repainted.	No	Hood is Repainted.	No
Back bumper is repainted.	No	Right Fender is Repainted.	No
Right Front Door is repainted.	No	Right quarter Panel is Repainted.	No
Left Front Door is repainted.	No	Left quarter panel is repainted.	No
Right Rear Door is Repainted.	No	Left Rocker is repainted.	No
Right Rocker is repainted.	No		

### EXTERIOR COMPONENTS

All door handles are operating properly.	Yes	Wipers are working properly.	Yes
--	-----	------------------------------	-----

### GLASSES

No scratch & cracks on windshields and windows.	No
---	----

### LIGHTS

Head lights, Tail lights and other lights functioning normally.	Yes
Head lights don't have any moisture formation.	Yes

## Interior

### AIR CONDITIONER

Vent air flow operate as designed.	No
Heating & Air Cooling condition operating as designed.	No

### BODY PANEL

No scratch, dent or discoloration in interior body panels.	No
No Rusting in trunk floor.	No

### INTERIOR COMPONENTS

Interior door handles are operating properly.	Yes
Horn is functioning properly.	Yes
All knobs and switches are operating smoothly.	Yes

### SEATS

No stain, wear & tear in seats.	No
---------------------------------	----

## Engine

<b>BATTERY</b>			
Battery condition is good.			Yes
<b>FIXTURES</b>			
No bodywork or rusting in the firewall.			No
No rusting or bodywork in apron.			No
Factory bolts and seals of bonnet frame are intact.			No
<b>HEALTH</b>			
Engine is intact and no overhauling done before.			No
No blowback observed in the Engine.			No
Engine is free of oil leakage.			Yes
<b>Road Test</b>			
<b>MALFUNCTION</b>			
No abnormal noise from engine.	No	No abnormal noise from gear box.	No
No abnormal noise from tyre.	No	No noise or leakage from axle.	No
<b>PEDAL</b>			
Transmission/ clutch operates properly with no slipping.			Yes
Brake is functioning properly with no slipping and free of noise.			Yes
<b>STABILITY</b>			
Vehicle doesn't pull to the side when brake is applied.			Yes
Vehicle drives straight on level surface.			Yes
<b>SUSPENSION</b>			
No abnormal noise or vibration from suspension.			No
<b>Tyres</b>			
<b>FRONT LEFT TYRE</b>			
No cut marks or hardening is observed in tyre.			No
No scratch, rusting and damage observed in rim.			No
<b>FRONT RIGHT TYRE</b>			
No cut marks or hardening is observed in tyre.			No
No scratch, rusting and damage observed in rim.			No
<b>REAR LEFT TYRE</b>			
No cut marks or hardening is observed in tyre.			No
No scratch, rusting and damage observed in rim.			No
<b>REAR RIGHT TYRE</b>			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			No
<b>SPARE TYRE</b>			
Spare tyre is present.			Yes