

# Inspection Report-2018 Maruti Swift Dzire LDI

## Exterior

### Body

No Rusting on outer body panels.	Yes	Left Rear Door is repainted.	Yes
Right side pillar A, B & C has no damage and factory seal intact.	Yes	Left Rear Door is Repaired.	Yes
Left side pillar A, B & C has no damage and factory seal intact.	Yes	Dickie is Repainted.	Yes
Front bumper is repainted.	Yes	Hood is Repainted.	Yes
Back bumper is repainted.	Yes	Right Fender is Repainted.	Yes
Right Front Door is repainted.	Yes	Right quarter Panel is Repainted.	Yes
Left Front Door is repainted.	Yes	Left quarter panel is repainted.	Yes
Right Rear Door is Repainted.	Yes	Left Rocker is repainted.	Yes
Right Rocker is repainted.	Yes		

### EXTERIOR COMPONENTS

All door handles are operating properly.	Yes	Wipers are working properly.	Yes
--	-----	------------------------------	-----

### GLASSES

No scratch & cracks on windshields and windows.	Yes
---	-----

### LIGHTS

Head lights, Tail lights and other lights functioning normally.	Yes
Head lights don't have any moisture formation.	Yes

## Interior

### AIR CONDITIONER

Vent air flow operate as designed.	Yes
Heating & Air Cooling condition operating as designed.	Yes

### BODY PANEL

No scratch, dent or discoloration in interior body panels.	Yes
No Rusting in trunk floor.	Yes

### INTERIOR COMPONENTS

Interior door handles are operating properly.	Yes
Horn is functioning properly.	Yes
All knobs and switches are operating smoothly.	Yes

### SEATS

No stain, wear & tear in seats.	Yes
---------------------------------	-----

## Engine

<b>BATTERY</b>			
Battery condition is good.			Yes
<b>FIXTURES</b>			
No bodywork or rusting in the firewall.			Yes
No rusting or bodywork in apron.			Yes
Factory bolts and seals of bonnet frame are intact.			Yes
<b>HEALTH</b>			
Engine is intact and no overhauling done before.			Yes
No blowback observed in the Engine.			Yes
Engine is free of oil leakage.			Yes
<b>Road Test</b>			
<b>MALFUNCTION</b>			
No abnormal noise from engine.	Yes	No abnormal noise from gear box.	Yes
No abnormal noise from tyre.	Yes	No noise or leakage from axle.	Yes
<b>PEDAL</b>			
Transmission/ clutch operates properly with no slipping.			Yes
Brake is functioning properly with no slipping and free of noise.			Yes
<b>STABILITY</b>			
Vehicle doesn't pull to the side when brake is applied.			Yes
Vehicle drives straight on level surface.			Yes
<b>SUSPENSION</b>			
No abnormal noise or vibration from suspension.			Yes
<b>Tyres</b>			
<b>FRONT LEFT TYRE</b>			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			Yes
<b>FRONT RIGHT TYRE</b>			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			Yes
<b>REAR LEFT TYRE</b>			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			Yes
<b>REAR RIGHT TYRE</b>			
No cut marks or hardening is observed in tyre.			Yes
No scratch, rusting and damage observed in rim.			Yes
<b>SPARE TYRE</b>			
Spare tyre is present.			Yes